


ENGLISH

Mounting Instructions



FS62WSS, FS62WSR, FS63WTS

**Weldable Strain Sensor and Rosette and
Weldable Temperature Sensor**

HBK FiberSensing, S.A.
Via José Régio, 256
4485-860 Vilar do Pinheiro
Portugal
Tel. +351 229 613 010
Fax +351 229 613 020
info.fs@hbkworld.com
www.hbkworld.com

Mat.:
DVS: A05037 03 E00 00
02.2025

© Hottinger Brüel & Kjaer GmbH

Subject to modifications.
All product descriptions are for general information
only. They are not to be understood as a guarantee of
quality or durability.

TABLE OF CONTENTS

1	General information	4
1.1	Environment Considerations	5
1.1.1	Packaging Disposal	5
1.2	Marking used in this document	7
2	Sensor installation	9
2.1	Introductory notes	9
2.2	List of materials	9
2.3	Installation of FS62WSS	10
2.3.1	Preparation of the installation area	10
2.3.2	Marking the measuring point	14
2.3.3	Positioning the sensor	15
2.3.4	Welding procedure	16
2.4	Installation of FS62WSR	22
2.4.1	Preparation of the installation area	22
2.4.2	Marking the measuring point	22
2.4.3	Positioning the sensor	23
2.4.4	Welding procedure	24
2.5	Installation of FS63WTS	28
2.5.1	Preparation of the installation area	28
2.5.2	Marking the measuring point	28
2.5.3	Positioning the sensor	28
2.5.4	Welding procedure	29
2.6	Routing and protecting the cables	31
2.7	Protecting the sensor	32
3	Sensor configuration	34
3.1	Sensors documentation	34
3.2	Measurement computation	34
3.2.1	Temperature	34
3.2.2	Strain	36
4	Sensor Maintenance	44
4.1	Sensor	44
4.1.1	Strain Sensor	44
4.1.2	Temperature Sensor	44
4.2	Cables	44
4.3	Connectors	45

1 GENERAL INFORMATION

The following instructions refer to the installation procedure of FS62WSS Weldable Strain Sensors, FS62WSR Weldable Strain Rosette and FS63WTS Weldable Temperature Sensors.

These sensors can be delivered individually or in arrays of sensors preassembled at HBK FiberSensing facilities.

Material numbers

Strain Sensors	Strain Rosettes	Temperature Sensors
K-FS62WSS	K-FS62WSR	K-FS63WTS
1-FS62WSS-ARM/1510	1-FS62WSR-ARM/3505	1-FS63WTS-ARM/1515
1-FS62WSS-ARM/1520	1-FS62WSR-ARM/3520	1-FS63WTS-ARM/1525
1-FS62WSS-ARM/1530	1-FS62WSR-ARM/3535	1-FS63WTS-ARM/1535
1-FS62WSS-ARM/1540	1-FS62WSR-ARM/3550	1-FS63WTS-ARM/1545
1-FS62WSS-ARM/1550	1-FS62WSR-ARM/3565	1-FS63WTS-ARM/1555
1-FS62WSS-ARM/1560	1-FS62WSR-ARM/3580	1-FS63WTS-ARM/1565
1-FS62WSS-ARM/1570		1-FS63WTS-ARM/1575
1-FS62WSS-ARM/1580		1-FS63WTS-ARM/1585
1-FS62WSS-ARM/1590		1-FS63WTS-ARM/1595

Sensor Arrays ¹⁾	
K-FS76ARD	K-FS76ARM

¹⁾ Only FS62WSS and FS63WTS have Sensor Arrays. For arrays of sensors including FS62WSR strain rosettes please contact HBK FiberSensing.

Information

This document is focusing on the installation of the FS62WSS and FS62WSR on its aramid and armor versions. The installation of these sensors with braided cable is similar, except for apparent difference in shape, size and cable handling. For detailed mounting instructions of the FS62WSS Weldable Strain Sensor or FS62WSR Weldable Strain Rosette with braided cable please refer to the specific installation instructions.

1.1 Environment Considerations

1.1.1 Packaging Disposal

The packaging of this equipment is designed to protect it from damage during transportation and storage. It is also made of materials that can be recycled or reused, in accordance with the European Union's waste management regulations to minimize its environmental impact.

If you plan to move your equipment to different locations it is advisable that you keep the original package for reuse. This will not only grant proper protection for transportation, but also ensure the reduction of waste creation.

Packing boxes include a label with information on the materials used on that specific package.



Fig. 1.1 Packing label example

Please follow the instructions below to dispose of the packaging properly and responsibly and contribute to the preservation of our planet. Thank you!

To dispose of packaging, you should:

- Remove any labels, adhesives, nails, staplers or caps that are not part of the same material.
- Rinse the packaging with water to remove any residues or dirt.
- Flatten or fold the packaging to reduce its volume and save space (except for glass that should not be crushed).
- Separate the packaging by material and place it in the appropriate recycling bin or bag.

Most of our packing are made of paper and plastic and aimed to be reused or recycled, but they are not appropriate for food containing. Please consult the chapter “Packing Symbols” for more detailed information about the packing materials used by HBK FiberSensing, marked in the packing label of each product delivered to customers.

Packaging Symbols

Packing materials are marked with the correspondent symbol for guidance.



Not appropriate for food



Recyclable

The recycling symbols for the different materials include numbers and letters that identify the material type. For example, PET (polyethylene terephthalate) is marked also with the number 1, and PE-HD (high-density polyethylene) is marked with the number 2. For paper (PAP) 20 corresponds to corrugated cardboard and 22 to paper as seen in newspapers, books,...




Fig. 1.2 Recycling symbols

Plastics

Plastic packaging materials are commonly bags, films, trays, blisters or containers.

Batteries

Batteries are not part of the packaging, but they may be included in the equipment or its accessories. HBK FiberSensing sensors do not include batteries.

Paper

Paper packaging materials are commonly boxes, cartons, envelopes, or labels.

Metals

Metal packaging materials are commonly cans, foils, caps, or wires.

Organic

Organic packaging materials could be wood, cork, or cotton and are made of natural or biodegradable materials that can be composted or reused.

Glass

Glass packaging materials are bottles, jars, or vials.

Composites

Composite packaging materials are made of layers of different materials, such as paper, plastic, and aluminum. They are marked with a recycling symbol and a letter that indicates the composition of the packaging. For example, PAP is for paper and plastic, and ALU is for aluminum.

1.2 Marking used in this document

Important instructions for your safety are specifically identified. It is essential to follow these instructions to prevent accidents and property damage.

Symbol	Significance
 CAUTION	This marking warns of a <i>potentially</i> dangerous situation in which failure to comply with safety requirements <i>can</i> result in slight or moderate physical injury.
 Notice	This marking draws your attention to a situation in which failure to comply with safety requirements <i>can</i> lead to damage to property.
 Important	This marking draws your attention to <i>important</i> information about the product or about handling the product.
 Tip	This marking indicates application tips or other information that is useful to you.
 Information	This marking draws your attention to information about the product or about handling the product.

Symbol	Significance
<i>Emphasis</i> See ...	Italics are used to emphasize and highlight text and identify references to sections, diagrams, or external documents and files.
▶	This marking indicates an action in a procedure

2 SENSOR INSTALLATION

2.1 Introductory notes

When mounting FS62WSS, FS62WSR and FS63WTS sensors, please pay attention to the following:

- Handle with care.
These are precision sensors and so their achievable accuracy highly depends on correct mounting.
- Do not overload the sensors.
- Avoid lateral forces or torque.
- Handle the cables with care before fixing to avoid damage. Do not hold the sensor by the cables.
- Use the appropriate tools and machines for the proper welding of the sensor. Poorly welded strain sensors will compromise the correct reading.

Notice

The FS62WSS, FS62WSR and FS63WTS sensors are precision measuring elements and need to be handled carefully. Dropping or knocking the sensors may cause permanent damage. Make sure that the sensors cannot be overloaded, including while they are being mounted.

2.2 List of materials

Included material

FS62WSS	FS62WSR	FS63WTS
Sensor Weldable cable ties Weldable plate sample(s)	Rosette Weldable cable ties Weldable plate sample(s)	Sensor Weldable cable ties Weldable plate sample(s)

Needed equipment

Deburring Machine (optional)
Impulse Welding Device Recommended: similar to c33 from VBS Fuegetechnik

Needed material

Sandpaper.
Surface cleaning agents. Recommended HBK: 1-RMS1 or 1-RMS1-SPRAY
Tissues. Recommended HBK: 1-8402.0026
Drafting tape. Recommended HBK: 1-KLEBEBAND
Protection. Recommended HBK: 1-ABM75 and/or AK22

2.3 Installation of FS62WSS



Fig. 2.1 FS62WSS Weldable Strain Sensor

2.3.1 Preparation of the installation area

Remove all the paint and rust from the installation area until reaching a weldable material (Fig. 2.2). Ensure that there are neither irregularities nor debris left on the surface, as this would compromise the welding process. If needed regularize the surface in detail using a sanding paper.



Fig. 2.2 Surface deburring



Tip

Use the dummy sensor plate to define the area to prepare



Fig. 2.3 Uneven and rusty surface unsuited for welding sensor



Fig. 2.4 Surface Sanding



Fig. 2.5 Ready to weld surface

The surface needs to be cleaned ensuring that no dust nor grease is present in the welding area.

Clean the surface using and appropriate cleaner degreaser (RMS 1 is suggested) and nonwoven tissues (*Fig. 2.6 and Fig. 2.7*).



Fig. 2.6 Using RMS1 cleaner and nonwoven tissues



Fig. 2.7 Cleaning the surface

The wiping movements should always be performed in the same direction until the last tissue comes out clean.

2.3.2 Marking the measuring point

Define the alignment of the sensor considering the measurement direction and the sensor's central guidelines. This step is particularly important for the strain sensor as the sensor positioning dictates the measurement direction.




Fig. 2.8 Sensor alignment markings



Tip

Use a sharp tool or a pen, depending on the surface material, to mark the sensor position.

The length of the marking line should be approx. 150 mm in the measurement direction. A vertical marking line, approx. 50 mm long, must be drawn starting at the center of the installation point, see Fig. 2.8 and Fig. 2.9.



Fig. 2.9 Marking the sensor position

2.3.3 Positioning the sensor

Prepare four pieces of an appropriate tape (example, masking tape). Two long enough to secure the cables and the other two to secure along the sensor.



Fig. 2.10 Securing tape preparation

Carefully remove the sensor from the blister and align it with the drawn marks.

Using the smaller prepared tape pieces, secure the sensor cables in place (*Fig. 2.11*)



Fig. 2.11 First alignment

Use the larger tape pieces to fix the sensor, along its longer side, using the larger cable strain relief areas. This will ensure that the sensor will not move during the welding process.

Notice

Ensure that welding area is free from tape. Performing the welding on areas with tape or glue will create an interference on the discharge that might ruin the sensor.




Fig. 2.12 Ensuring a smooth welding process by thoroughly fixing the sensor

2.3.4 Welding procedure

HBK FiberSensing recommends the use of a c33 model from VBS Fuegetechnik.



Fig. 2.13 Recommended impulse welding device

Testing welding settings

Ideal welding settings may vary (depending not only on the used spot welder but also on material thickness, electrode position...). For that reason dummy welding plates for recipe tuning are delivered. Adjust the welding parameters by testing on the cleaned area away from the sensor position.

Spot weld the dummy plate and pull it to detach from the surface. For a good welding, this should be difficult to achieve and, once detached, the welding points should have become holes on the dummy plate as depicted in *Fig. 2.14*.



Fig. 2.14 Correct welding settings confirmation



Tip

Common settings should be with voltage between 40 V and 60 V.

It is recommended that the electrode tip is trimmed flat and with approximately 1mm diameter (*Fig. 2.15*).



Fig. 2.15 *Electrode tip*



Tip

Frequently trim the electrode during the welding procedure for the best results.

While welding, press down the welding pistol vertically (as shown in Fig. 2.16), one hand holding the pistol and the heel of the other hand pressing down the pistol from atop with force.



Fig. 2.16 *Correct welding position*

Welding the sensor

The weldable strain sensor must be thoroughly welded to the structure along the central area where the sensing FBG is. The FS62WSS on its aramid or armor cable option feature a cable anchorage at the extremes that is prepared to be secured to the structure while providing strain relief in case the cables get pulled.



Fig. 2.17 FS62WSS welding areas

- 1 Sensor strain transfer welding area
- 2 Cable strain relief welding area

The welding sequence should be performed from the middle to the outside of the sensors with points spaced at approximately 1 mm.

Follow the path as presented in Fig. 2.18 .




Fig. 2.18 FS62WSS welding procedure




Fig. 2.19 Welding the sensor



Tip

When completely welded the FS62WSS on its aramid or armor cable version should have around 31 welding points per line.




Fig. 2.20 Complete welding

Remove the tapes and secure the fiber cables with the provided steel clips (see Fig. 2.21).



Fig. 2.21 Welded sensor with steel clips

2.4 Installation of FS62WSR




Fig. 2.22 FS62WSR Weldable Stain Rosette

2.4.1 Preparation of the installation area

Proceed with the surface cleaning as described in section 2.3.1

"Preparation of the installation area", page 10, using the dummy plate as a reference to define the surface area that needs to be cleaned.

2.4.2 Marking the measuring point

The FS62WSR Rosette has three FBGs in a $0^\circ/60^\circ/120^\circ$ position. The alignment of each FBG is evidenced by the sensor guides present at each corner of the rosette, which are defined as directions "a", "b" and "c", as shown in Fig. 2.23.




Fig. 2.23 Rosette alignment markings

2.4.3 Positioning the sensor

Prepare four pieces of an appropriate tape (example, masking tape). Three long enough to secure the three sides of the rosette triangle, and the fourth one to secure the cables.



Fig. 2.24 Securing tape preparation

Position the optical rosette on the marking cross. Align the desired direction, for example "b", with the horizontal marking. Refer to the alignment marks present on the sensor base to support on this positioning. Then align the perpendicular direction, for example between the lines pointing to the center of the "b" direction and the cable exiting between "a" and "c" directions.



Fig. 2.25 Aligned and tape secured FS62WSR

Secure the rosette in place using the tape by applying the tape along the sides covering about one millimeter.

Notice

Ensure that welding area is free from tape. Performing the welding on areas with tape or glue will create an interference on the discharge that might ruin the sensor.

2.4.4 Welding procedure

Testing welding settings

Start by testing the welding settings following the procedure described in section 2.3.4 "Welding procedure", page 16.

Welding the rosette

The weldable strain rosette must be thoroughly welded to the structure along the three measuring directions where the sensing FBGs are. The FS62WSR on its aramid or armor cable option feature a cable anchorage at cable exiting vertex that is prepared to be secured to the structure while providing strain relief in case the cables get pulled.




Fig. 2.26 FS62WSR welding areas

- 1** Sensor strain transfer welding area
- 2** Cable strain relief welding area

The welding sequence should be performed from the middle to the outside of each of the FBG alignments with points spaced at approximately 1 mm.

Follow the path as presented in *Fig. 2.27*. Repeat for the remaining measuring directions (*Fig. 2.28*). After that, proceed with welding the strain relieve points (*Fig. 2.29*).




Fig. 2.27 FS62 WSR welding path 1




Fig. 2.28 FS62 WSR welding path 2




Fig. 2.29 FS62WSR welding path 3



Tip

When completely welded the FS62WSR on its aramid or armor cable version should have around 35 welding points, on the outside line, per orientation.



Fig. 2.30 FS62WSR welding procedure

Finally, secure the fiber cables with the provided steel clips (Fig. 2.31).



Fig. 2.31 FS62WSR with steel clips

2.5 Installation of FS63WTS




Fig. 2.32 FS63WTS Weldable Temperature Sensor

2.5.1 Preparation of the installation area

For the installation of the FS63WTS Weldable Temperature Sensor, the surface must be clean and without irregularities. Please follow the procedures as described on section 2.3.1 "Preparation of the installation area", page 10.

2.5.2 Marking the measuring point

Please follow procedures as described on section 2.3.2 "Marking the measuring point", page 14.

2.5.3 Positioning the sensor

Please follow procedures as described on section 2.3.3 "Positioning the sensor", page 15.

2.5.4 Welding procedure

Testing welding settings

Start by testing the welding settings following the procedure described in *section 2.3.4 "Welding procedure"*, page 16.

Welding the sensor

The weldable temperature sensor does not require the full welding, as there is no need for adding strain to the sensor body. Throughout the sensor body and at the extremes the sensor is prepared with strain relief points.




Fig. 2.33 FS63CTS welding areas

- 1 Sensor body strain relief welding area
- 2 Cable strain relief welding area

The welding sequence should be performed from the middle to the outside of the sensors at the strain relief tabs.

Follow the path as presented in *Fig. 2.23*. When the full length of the sensor is welded on both sides, proceed with welding the cable strain relieve points.




Fig. 2.34 FS63WTS welding path

After Welding secure the fiber cables with the provided steel clips (see Fig. 2.21, page 22) and then proceed to routing and protecting the cables.

2.6 Routing and protecting the cables

Sensor cable should be routed ensuring that cables are not hanging and curvatures are kept within the limits for the used cable. The cable should be fixed by means of clamps or strong tape, for example (Fig. 2.35). In case there are splice protections, ensure that the splices are also well fixed.



Fig. 2.35 Cable routing

Plastic corrugated tubes can also help routing the longer lead cables that will connect to the interrogator (Fig. 2.36).



Fig. 2.36 Cable protected with corrugated tubes

Excess cable should be coiled and stored in a suitable IP case, so it can be used in case of network refurbishment (*Fig. 2.37*).



Fig. 2.37 Protection boxes for extra cable and connections

2.7 Protecting the sensor

The FS62WSS, FS62WSR and FS63WTS sensors are ruggedized sensors produced with stainless steel. Nevertheless, the structure surface and the welding points are sensitive areas where corrosion is prone to occur. It is then advisable to further protect the sensor areas and the deburred area for moisture.

Recommendations for protection are the HBK AK22 putty adhesive (*Fig. 2.38*) and/or ABM75 (*Fig. 2.39*).



Fig. 2.38 Sensor protected with AK22



Fig. 2.39 *Sensor protected with ABM75*

3.1 Sensors documentation

Calibrated HBK FiberSensing Sensors are delivered with a Calibration Sheet. Remaining sensors are delivered with a sensor Characteristic Sheet that contains important information for sensor configuration.

In the case sensors are delivered in arrays of pre-assembled sensors, a resume table with the relevant calibration information is provided in alternative.

Within the sensor's packing this installation instructions document is delivered in a printed version. Installation instructions can also be downloaded from HBK website (www.hbm.com).

3.2 Measurement computation

3.2.1 Temperature

The calculations that should be performed for converting a wavelength measurement into temperature are the shown in *Fig. 3.1*. The temperature value measured with a temperature sensor is given by a second order polynomial equation with coefficients obtained from the sensor calibration.

$$T = S_2(\lambda - \lambda_0)^2 + S_1(\lambda - \lambda_0) + S_0$$

Fig. 3.1 Temperature computation formula

Where

- T is the measured Temperature in °C
- λ is the measured Bragg wavelength of the temperature sensor in nm
- λ_0 is the Bragg wavelength of the temperature sensor at reference temperature in nm
- S_0 is the zero order calibration factor (reference temperature) in °C
- S_1 is the first order calibration factor in °C/nm
- S_2 is the second order calibration factor in °C/nm²

When operating with catman® the values λ_0 , S_0 , S_1 and S_2 should be filled on the menu for temperature sensors configuration.

Measurement with Distance Effect Correction

When measuring with sweeping laser-based Optical Interrogators, such as the BraggMETER from HBK FiberSensing, the length of cabling between the interrogator and

the sensor affects the measured reflected signal. This distance error is significant for sensors that rely on absolute wavelength values, such as temperature sensors.

The sweeping laser emits a varying wavelength over time. The method for measuring the reflected wavelength from the fiber Bragg grating (FBG) sensor identifies the wavelength being emitted at the time the reflected peak from the FBG is detected. As the acquisition rate increases, the delay caused by the distance the light travels both ways becomes more pronounced, reducing the accuracy of the absolute wavelength measurement. The same effect occurs with increasing distances.

The cable length effect manifests as a constant shift in the wavelength measurement, which depends on the sampling rate of the optical module and the distance between the sensor and the interrogator. The shift in the measured wavelength is negligible for low acquisition rates or short distances but becomes significant for high sampling rates or long distances.

$$\Delta\lambda_{error} = \frac{d \cdot 2 \cdot n \cdot RepRate \cdot FullRange}{SweepDirection \cdot DutyCycle \cdot c}$$

Fig. 3.2 Wavelength shift due to sweeping laser speed

Where:

- $\Delta\lambda_{error}$ is the wavelength "error", in nm;
- d is the distance (in m) between the sensor and the measurement unit;
- n is the refraction index of the fiber (1.446 for standard SMF28 fiber);
- $RepRate$ is the optical module actual acquisition scan (for BraggMETER interrogators in the selected acquisition rate, in S/s);
- $FullRange$ is the length of the range of measured wavelengths (102 nm for BraggMETER interrogators);
- $SweepDirection$ is the signal of the sweeping direction: 1 for sweeping from the lowest to highest wavelengths and -1 for sweeping from the highest to lowest wavelengths;
- $DutyCycle$ is the sweeping portion of the cycle without flyback.
- c is the speed of light (3x10⁸ m/s).

A fixed temperature error caused by the distance can be calculated:

$$T_{error} = S_2 \times \Delta\lambda_{error}^2 + \Delta\lambda_{error}$$

and applied to the calibration formula for correction:

$$T = S_2(\lambda - \lambda_0)^2 + S_1(\lambda - \lambda_0) + S_0 - T_{error}$$

3.2.2 Strain

Strain sensors are not calibrated sensors. The characteristic sheet delivered with the sensor presents the sensor data for correct strain computation.

For the fiber Bragg grating strain sensors, wavelength variation including the effect of temperature is given by the equation shown in Fig. 3.3.

$$\frac{(\lambda - \lambda_0)}{\lambda_0} = k \cdot (\varepsilon_{Load} + (TCS + CTE) \cdot (T - T_0)) \cdot 10^{-6}$$

Fig. 3.3 Wavelength variation of a FBG strain sensor due to strain and temperature effects

Where

- λ is the measured Bragg wavelength of the strain sensor in nm
- λ_0 is the Bragg wavelength of the strain sensor at the reference instant in nm
- k is the strain k factor of the strain sensor, dimensionless
- ε_{Load} is the mechanical strain applied to the structure in $\mu\text{m/m}$
- TCS is the temperature cross sensitivity of the strain sensor in $(\mu\text{m/m})/^{\circ}\text{C}$
- CTE is the coefficient of thermal expansion of the material of the specimen the strain sensor is attached to in $(\mu\text{m/m})/^{\circ}\text{C}$
- $T - T_0$ is the difference between the actual temperature and the temperature at the reference instant in $^{\circ}\text{C}$

Measurement with no compensation

If no temperature compensation is required the strain computation can be done as shown in Fig. 3.4.

$$\varepsilon = \frac{(\lambda - \lambda_0)}{k \cdot \lambda_0} \cdot 10^6$$

Fig. 3.4 Simple strain computation formula (without temperature compensation)

Where

- ε is the measured strain in $\mu\text{m/m}$
- λ is the measured Bragg wavelength of the strain sensor in nm
- λ_0 is the Bragg wavelength of the strain sensor at the reference instant in nm
- k is the strain k factor of the strain sensor, dimensionless

Measurement with temperature compensation using a temperature sensor

Calculating compensated strain, in $\mu\text{m}/\text{m}$, using a temperature sensor is straightforward as the output of a temperature sensor is a temperature value in $^{\circ}\text{C}$. The calculation is depicted in Fig. 3.5.

$$\varepsilon_{\text{Load}} = \frac{(\lambda - \lambda_0)}{k \cdot \lambda_0} \cdot 10^6 - (TCS + CTE) \cdot (T - T_0)$$

Fig. 3.5 Strain computation with temperature compensation using a temperature sensor

Where

- $\varepsilon_{\text{Load}}$ is the mechanical strain applied to the structure in $\mu\text{m}/\text{m}$
- λ is the measured Bragg wavelength of the strain sensor in nm
- λ_0 is the Bragg wavelength of the strain sensor at the reference instant in nm
- k is the strain k factor of the strain sensor, dimensionless
- TCS is the temperature cross sensitivity of the strain sensor in $(\mu\text{m}/\text{m})/^{\circ}\text{C}$
- CTE is the coefficient of thermal expansion of the material of the specimen the strain sensor is attached to in $(\mu\text{m}/\text{m})/^{\circ}\text{C}$
- T is the actual temperature measured by the temperature sensor used for compensation in $^{\circ}\text{C}$
- T_0 is the temperature measured by the temperature sensor used for compensation at the reference instant in $^{\circ}\text{C}$




Fig. 3.6 Reference instant for temperature compensated strain measurement when using a temperature sensor for compensation

Measurement with temperature compensation using a compensation element

Strain measurement can also be correctly compensated using a compensation element based on FBG technology. Different approaches can be used:

- a temperature sensor without calibration certificate
- a strain sensor installed on a strain-free area of the same material
- a strain sensor installed on a strain-free material with a known CTE

The computation of strain can then be performed using the equation from Fig. 3.7.

$$\varepsilon_{Load} = \frac{\lambda - \lambda_0}{k \cdot \lambda_0} \cdot 10^6 - \frac{\lambda_{TC} - \lambda_{0_{TC}}}{\lambda_{0_{TC}}} \cdot \frac{(TCS + CTE)}{TCF} \cdot 10^6$$

Fig. 3.7 Strain computation with temperature compensation using an FBG compensation element

Where

- ε_{Load} is the mechanical strain applied to the structure in $\mu\text{m/m}$
- λ is the measured Bragg wavelength of the strain sensor in nm
- λ_0 is the Bragg wavelength of the strain sensor at the reference instant in nm
- k is the strain k factor of the strain sensor, dimensionless
- λ_{TC} is the measured Bragg wavelength of the compensation element in nm

- λ_{0TC} is the Bragg wavelength of the compensation element at the reference instant in nm
- TCS is the temperature cross sensitivity of the strain sensor in $(\mu\text{m}/\text{m})/^{\circ}\text{C}$
- CTE is the coefficient of thermal expansion of the material of the specimen the strain sensor is attached to in $(\mu\text{m}/\text{m})/^{\circ}\text{C}$
- TCF is the temperature compensation factor of the compensation element in $(\mu\text{m}/\text{m})/^{\circ}\text{C}$. For an uncalibrated temperature sensor this value is given on the sensor's characteristics sheet. For a strain sensor attached to a specific material TCF can be calculated as shown in Fig. 3.8.

$$TCF = (5.7 + k \cdot CTE_{TC})$$

Fig. 3.8 Temperature compensation factor computation

Where

- k is the strain k factor of the strain sensor attached to the temperature compensation element, dimensionless
- CTE_{TC} is the coefficient of thermal expansion of the material of the temperature compensation element in $(\mu\text{m}/\text{m})/^{\circ}\text{C}$




Fig. 3.9 Reference instant for temperature compensated strain measurement when using an FBG compensation element

Measurement with bending moment correction

When measuring on an element using a sensor that is far away from the attachment surface there may be an “error” on the measurement because the distance between the measuring point/alignment and the neutral axis is different to the distance between the installation surface and the neutral axis.




Fig. 3.10 Strain on pure axial deformation




Fig. 3.11 Strain on pure bending moment




Fig. 3.12 Strain on axial load and bending moment

This becomes of high importance when the distance between the sensing element on the sensor to the attachment surface is relevant, or the measuring object is very thin. This distance on the FS62WSS Weldable Strain Sensor and FS62WSR Weldable Strain Rosette is 0.25 mm (h_2 on Fig. 3.12).




Fig. 3.13 Distance of the FBG to the mounting surface on the FS62WSS

However, knowing the distance to the neutral axis (h_1) the measured strain from the sensor can be corrected into strain on the surface by a geometrical factor:

$$\varepsilon_{surface} = \frac{\lambda - \lambda_0}{k \cdot \lambda} \cdot \frac{h_1}{h_2 + h_1} \cdot 10^6$$

Fig. 3.14 Strain computation bending effect correction

Where

- $\varepsilon_{surface}$ is the mechanical strain on the measuring surface in $\mu\text{m/m}$
- λ is the measured Bragg wavelength of the strain sensor in nm
- λ_0 is the Bragg wavelength of the strain sensor at the reference instant in nm
- k is the strain k factor of the strain sensor, dimensionless
- h_1 is the distance from the measuring surface to the neutral axis in mm
- h_2 is the distance from the measuring surface to the FBG in mm (0.225 mm for the FS62WSS and FS62WSR)

Measuring principal stresses

Principal stresses computation with the FS62WSR Weldable Strain Rosette can be calculated in accordance to the equation:

$$\sigma_{1/2} = \frac{E}{1 - \nu^2} \cdot \frac{\varepsilon_a + \varepsilon_b + \varepsilon_c}{3} \pm \frac{E}{1 + \nu} \sqrt{\left(\frac{2\varepsilon_a - \varepsilon_b - \varepsilon_c}{3}\right)^2 + \frac{1}{3} \cdot (\varepsilon_b - \varepsilon_c)^2}$$

Where:

- $\sigma_{1/2}$ are the principal stresses, in MPa
- E is the young modulus, in GPa
- ν is the Poisson ration, dimensionless
- $\varepsilon_{a/b/c}$ are the the strains measured by the rosette on the three directions, in $\mu\text{m/m}$

The principal directions are the directions in which the principal normal stresses σ_1 and σ_2 occur as calculated using the equation above. Principal normal stress directions are defined by the angle φ that refers to the rosette's measuring directions, which can be determined using geometrical relationships from the strains ε_a , ε_b and ε_c measured with the rosette.

The aim of the following treatment is to provide the practical engineer with a convenient and reliable method. The theoretical aspects of Mohr's Stress Circle, which forms the basis of this treatment, are described in general literature.

First a tangent of an auxiliary angle ψ is calculated:

$$\tan \psi = \frac{\sqrt{3} \cdot (\varepsilon_b - \varepsilon_c)}{2\varepsilon_a - \varepsilon_b - \varepsilon_c}$$

Considering the signals of the numerator and denominator, the angle φ should be determined using the following scheme:

		Numerator $\sqrt{3} \cdot (\varepsilon_b - \varepsilon_c)$	
		Negative	Positive
Denominator $2\varepsilon_a - \varepsilon_b - \varepsilon_c$	Positive	$\varphi = \frac{1}{2} \cdot (180^\circ - \psi)$	$\varphi = \frac{1}{2} \cdot (0^\circ + \psi)$
	Negative	$\varphi = \frac{1}{2} \cdot (180^\circ + \psi)$	$\varphi = \frac{1}{2} \cdot (360^\circ - \psi)$

The angle φ found in this manner should be applied from the axis of the reference measuring position a in the mathematically positive direction (counter-clockwise). The axis of the measuring direction "a" forms one arm of the angle φ . The other arm represents the first principal direction. This is the direction of the principal normal stress σ_1 (identical with the principal strain direction ε_1). The point of the angle is located at the intersection of the axes perpendicular to the measuring directions. The second principal direction (direction of the principal normal stress σ_2) has the angle $\varphi + 90^\circ$.




Fig. 3.15 Principal strain directions

4 SENSOR MAINTENANCE

4.1 Sensor

4.1.1 Strain Sensor

Weldable strain sensors, by principle, cannot be repaired after installation. If a strain sensor, whether linear or rosette, is damaged during or after installation, the solution is to completely replace the sensor. It is not expected that a strain sensor will be damaged under regular operating conditions. More commonly, damage occurs to the connections rather than the sensor itself.

4.1.2 Temperature Sensor

For temperature sensors, it might be possible to remove and reinstall the same sensor without causing damage, depending on the attachment method used. If welded, it is unlikely that the sensor can be removed without irreversible damage. However, if secured with polyimide tape or cable ties, it might be possible to retrieve the sensor without further damage.



Tip

Carefully remove any covering agents that may act as glue and damage the sensor during removal.

Temperature sensors can be completely damaged beyond repair in cases of severe incidents (mechanical shock, extremely high temperatures, etc.). However, recalibration may be necessary if the sensor has been subjected to temperatures higher than specified for short periods.

If it is possible to remove the installed sensor and an offset is observed, please contact HBK FiberSensing to discuss recalibration options. Note that recalibration performed by HBK FiberSensing may be subject to a fee.

4.2 Cables

If a cable is damaged during installation or use, a local repair might be possible. However, the feasibility of the repair depends on the location of the damage. If the damage is too close to the sensor, there may not be enough cable length available to use the splicing tools, making the repair unfeasible.

When a repair is feasible and there is sufficient cable length, you can cut the cable to remove the damaged section and perform a splice on the fiber cable. If there isn't enough cable length, you will need to insert an extension and perform two splices. Please contact HBK FiberSensing for support with the splicing procedures.

When sensors are delivered in an array and a cable is damaged between two sensors, you will lose signals from all sensors past the damage. Cables can be repaired as described above.



Tip

If no repair is possible, it might be possible to recuperate some signals when connection redundancy exists. If the fiber can be interrogated from both ends, ensure that there is no light propagation at the location of the damage (by fully cutting the fiber connection) and insert a splitter between the optical connector of the interrogator and the two ends of the sensor array.

4.3 Connectors

If a connector is damaged, it can be replaced either by performing a local splice or by returning the sensor for reconnection. Note that repairs performed by HBK FiberSensing may be subject to a fee.

